



REMOVE HEX SPACERS (IF FITTED) FROM FEMALE CONNECTOR



9 WAY D SKT VIEW

Notes:

- Cut off the male connector from item 1 and discard.
- Cut back and insulate any unused wires within the Hirose connector using item 5.
- Insulate all joints using item 5.

NOTE: WIRE COLOURS MAY CHANGE AND SHOULD BE CHECKED FOR CORRECT CONTINUITY BEFORE ASSEMBLY

BILL OF MATERIALS

ITEM	QTY	SUPPLIER	PART NUMBER	DESCRIPTION	RLPN
1	1	CPC	1C51-1-2M-43	9 WAY D TYPE LEAD	1C51-1-2M-43
2	1	AVERY	J8658-25	CABLE IDENT ON 25.4 x 10mm LABEL	
3	1	FARNELL	304-6539	CLEAR HEATSHRINK 6mm	304-6539
4	1	Hirose	HR30-6P-6P	Hirose HR30 6W Plug	142-5745
5	1	Pro Power	SP3X15/5/BLACK	1.5mm 3:1 Heatshrink Black	119-1021

CONNECTOR WIRING		
9 WAY D		Hirose HR30
PIN	WIRE	PIN
2	RED	2
3	ORANGE	1
5	GREEN	3

DRAWING NUMBER	RLCAB001-H	DRAWN	B.SELBY	SHEET	1/1
DESCRIPTION	VBOX SERIAL PC CABLE (HIROSE)				
REVISION					
ISS	DESCRIPTION	DATE	APPROVED	REDMINE	
1	FIRST ISSUE	12-05-21	RE	16781	